



ROCKFORD FIRE DEPARTMENT INCIDENT UPDATE

Incident Information:

Business Name:

Address of Incident: 1605 South Main Street

Date of Incident: September 1, 2013

Time of Incident: 08:52

Type of Incident: Residential Structure Fire

Cause of Fire: Undetermined

Estimated Loss: \$0.00

Injury Data:

Civilian Injuries: 0

Civilian Deaths: 0

Fire Department Response:

Engine(s): 3

Ladder(s): 1

District Chief(s): 2

Quint(s): 1

Ambulance(s): 1

Haz Mat Unit(s): 0

Boat(s): 0

Diver(s): 0

Other(s): 4

Total Firefighters: 26

Response Time: 2 min.

Narrative:

The Rockford Fire Department was dispatched to the address listed above for house fire. On arrival of the first units they encountered heavy fire on the entire second floor of the structure. Due to the structure being abandoned for a long period of time and deemed unsafe, a defensive attack was made. The structure was slated to be torn down due to the widening of South Main. No injuries were reported. The cause of the fire is undetermined at this time.

For additional information contact: Mark Marinaro 815-987-5678

Prepared by: Acting District Chief Frank Fuca 9/1/2013 12:10

